

Attachment A: Digital Images

Page 1 of 5

September 19th, 2008

BOE Building 1st Floor Janitor's Plenum Area

Sacramento, CA



- 1) Image of First Floor Janitor access doorway within BOE Building (Subject Building) located at 450 N Street, Sacramento.



- 2) Image of doorway leading to elevator lobby adjacent to janitor's room at time of inspection.



- 3) Image of marble wall material within elevator lobby area adjacent to shared wall of first floor janitor room area.



- 4) Image of stained flooring and cracking present within janitor's room at time of assessment.



5) Image of inspector access panel on ceiling within janitor's room.



6) Image of stained wallboard and plywood viewed from within janitor's plenum area at time of assessment.



- 7) Close-up image of stained plumbing and plumbing insulation materials located on western wall of janitor's plenum.



- 8) Image of staining trails and physical dripping from plumbing systems as viewed within the janitor's plenum area.



- 9) Additional image of plumbing structures and staining trails present on wallboard surfaces within western wall of janitor's plenum area.